

ਵੱਲੋਂ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲੋਂ

ਪ੍ਰਿੰਸੀਪਲ,
ਸਟੀਫਨ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ,
ਮਹਿਲਾਂ (ਸੰਗਰੂਰ)।

ਨੰ: 747


ਮਿਤੀ 28-4-22

ਵਿਸ਼ਾ: ਸਾਲ 2021-23 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ ਨਿੱਲ ਮਿਤੀ: 05.04.2022

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਦੀ ਰਿਪੋਰਟ ਦੇ ਆਧਾਰ ਤੇ ਸਕੂਲ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 31.03.2023 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ 18 ਮਿਤੀ 12.04.2022 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


Manager

Stephen International School
Mehlan (Sangrur) 148001


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Principal
Stephen International School
Mehlan (Distt. Sangrur)


Part-II


Building Safety Report


Name of School: Stephen International School, Mehlan, Tehsil-Sunam Distt. Sangrur.


This office Assistant Engineer Sh. Ashok Kumar Batta visited the above mentioned School Building and on visually inspection; it seems safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail; Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to One Year, upto 31.03.2023.


Assistant Engineer


Sub Divisional Engineer
Const. Sub Divn. No. 1, PWD.
B&RSangrur.


Manager
Stephen International School
Mehlan (Sangrur) 148001


Principal
Stephen International School
Mehlan (Distt. Sangrur)